Report of Test

Customer Details



Report No.

Unit 18, Millbrook Close St. James Mill Road Northampton NN5 5JF

Tel: +44 (0)1604 751146 Fax: +44 (0)1604 758062 Email: info@sutch.co.uk

age 21 of 38

D010441

INPORTANT NOTE.
This is a record of test only, an E.C. Declaration or
Report of Thorough Examination may also be
required prior to placing in service.

Site Address

								110	10771	
EUROPEAN COMMERCIAL VEHICLE ACCESSORIES LTD 22 STAPLEDON ROAD ORTON SOUTHGATE PETERBOROUGH CAMBS PE2 6TD				EUROPEAN COMMERCIAL VEHICLE AC 22 STAPLEDON ROAD ORTON SOUTHGATE PETERBOROUGH CAMBS PE2 6TD			Report Date	27 Nov 2014		
							Test Date	26 Nov 2014		
							Test Type	Destruction		
Job No.	Order Date	Order Date Customer		r Order Ref. Customer Contact		tact	<u></u>	Our Contact		
SV 234381	20 Nov 20				Yoav Ankin					
37 234361	20 1101 20	17			70077411431			L		
EQUIPMENT DETAILS										
	Description of the Item Tested			Quantity		Test Applied SWL		SWL		
Identification No or Reference No		Description of the from 100tou				Tested				
113458		Web Seat Belt 3000Kg Black				1	Tested To Destruction		Broke @ 4640 Kg	
I]								
I]					
:										
					İ					
									,	
Additional Test Details (including details of any defects found)										
									•	
									<u></u>	
Details of Any Standards\Technical Specifications Used										
Declaration.	Declaration. Authorised Signature									
						Nam				
I certify that the item/s described above have been tested in accordance with your										
instructions.						Date	27 Nov 20)14		







Incaffed -

Signature